


DUCT Mount Fitting

NOTES:

- 1/ Consult manual provided with Controller for specifics regarding calibration and separation distance.
- 2/ Follow instructions provided with Controller manual regarding wiring and safety requirements.



Place DUCT Mount Fitting over pilot holes and secure with sheet metal screws (4).

3

Place DUCT Mount Fitting over the hole and mark location of Mounting holes. Drill 1/4" pilot holes where marked.

2

WARNING: Secure on TOP or SIDE of ductwork only! NEVER install at bottom!

Select a flat section of ductwork and cut a hole (the approximate size of the sensor opening) where DUCT Mount Fitting is to be mounted.

1

Mounting holes (4)

4

Attach tubing to calibration fitting on DUCT Mount Fitting and run tubing down to Controller.